

General Info

Assignment No. 1394 Date/Time Inspected 10/22/2009 5:36:00 AM

Vehicle 1974 Plymouth Barracuda

Engine 340 V8 Drive RWD Trans manual 4spd

Tire Size Front 225/60R15 Tire Size Rear 245/60R15 OEM SizeUNKNOWN

Verified Vin BS23L4B207319

Verified Mileage

Body Exterior		Comments
Hood	OK	
Left Fender	OK	
Right Fender	OK	
Front Bumper	OK	
Grill/Nose Panel	OK	
Left Doors	OK	needs upper weather seal replaced
Right Doors	OK	
Left Quarter Panel	OK	
Right Quarter Panel	OK	has a new weather seal
Trunk Lid	OK	
Rear Bumper	OK	
Roof	OK	
Glass Condition	OK	
Signs of rust-give detail	OK	
Signs of body filler-detail	Not Reported	
Condition of Chrome	OK	EXCELLENT

Additional Comments

Restoration project was done very thoroughly, and well performed. The drivers for board sheet-metal was replaced. The left rear quarter panel area was replaced- patched. The trunk floor pan was replaced. All replacements appeared to be of an OEM type replacement panel. There are also some light sanding marks evident beneath the surface of the paint. Paint has very minimal orange peel. Body lines are very close. The driver door seems to be sagging just a little but normal for age (may need hinge pins) Driver's door rear quarter panel body line is slightly off. The driver's door upper window whether strips are worn and deteriorated (see pics). Overall, vehicle is in excellent condition rated four out of five.

Classic car condition evaluations rate this vehicle is being in good condition. Great daily driver looks good from a distance and close-up.

Interior Trim

		Comments
Dash	OK	
Door Trim	OK	
	OK	

Steering Wheel	OK	Torn see pics
Headliner	OK	
Seats	Needs Repairing	
Console	OK	
Evidence of Smoke/Odor	OK	
Carpet	OK	
Additional Comments		
Virtually all interior fabric, including carpet has been replaced recently is a little dusty and needs some detailing. There is a small tear in the drivers seat near the bottom rear of the seat only visible when seat is tilted forward for rear seat access. The rear seat cushion is a very small piece of fabric worn off at the center of the seat in the front. side window weather strips worn and need replaced.		
Interior Functions		Comments
Headlights	Needs Repairing	Left head lamp inop
Fog Lights	N/A	Right rear taillamp dim- possible ground
Park Lights	Needs Repairing	
TurnSignal	OK	
Interior Lights	OK	
Hazard Lights	N/A	Radio power on and played
Radio/CD Player	OK	
DVD	N/A	
Navigation	N/A	
Power Mirrors	N/A	All 4 window cranks worked well up and down
Power Windows	N/A	
Power Seats	N/A	
Power Locks	N/A	
Keyless	N/A	Did not test see below
Windshield Wipers	Not Reported	
Windshield Washers	Not Reported	
Horn	Not Reported	
Gauges	OK	open trunk with key - OK
Security	N/A	
Hood Release	OK	
Trunk Release	Not Reported	
Rear Defrost	N/A	
Air Conditioning	N/A	

Heater	OK
Sunroof	N/A
Vanity	N/A
Rear Wipers	N/A
Convertible	N/A

Additional Comments
 Windshield glass had a streak from the wipers from a recent swipe to show that they had worked previously, but did not turn wipers on due to not wanting to scratch the windshield without water also rear side marker lamps inop

Engine/Test Drive		Comments
Engine Noise/Smoke	OK	
Engine Performance	OK	
Check Engine Light	N/A	
Acceleration	OK	
Engine Temperature	OK	
Starting	OK	
Engine Oil Leaks/Odor	Not Reported	Minor leak see pics

Additional Comments
 Engine performance was very strong. Test drive limited to neighboring streets due to traffic, and there was no registration plate for the car at time of the inspection

Trans/Test Drive		Comments
Trans Performance	OK	
Transmission Leaks	OK	
Transmission Fluid	N/A	
Clutch	OK	

Additional Comments
 Transmission performed very well shifted smooth clutch appeared to be strong

Suspension System		Comments
Suspension Performance	OK	
Bounce Test	OK	

Bounce Test	
Suspension Noise	OK

Additional Comments

Suspension seemed very strong and tight. Undercarriage inspection appeared to be recent replacement for bushings and shocks

Steering System		Comments
Steering Performance	OK	
Steering Leaks	OK	
Steering Noise	OK	

Additional Comments

Brake System		Comments	
Braking Performance	OK		
Vibration When Braking	OK		
Brake Fluid Level Condition	OK		
Parking Brake	OK		Parking brake works
Brake Fluid Leaks	OK		

Additional Comments
Brake performance limited to around town type driving due to traffic patterns

Air Conditioning		Comments
Cooling Performance	N/A	
Evidence of Leaks	N/A	
Operating Noises	N/A	
Temperature Control	N/A	

Additional Comments

Drive Axles

Comments

Differential Leaks

OK

Axle Leaks

OK

CV Joint/Boot Condition

N/A

Noises Accelerating

OK

Noises On Turn

OK

Additional Comments

Wheels/Tires

Comments

Tires

OK

LF 10/32" RF 10/32" LR 10/32" RR 10/32"

Wheels

OK

Hub Caps / Wheel Covers

OK

Additional Comments

All tires are in new condition. All four wheels show absolutely no scrape scratches or damage - beauty rings are also in very good condition

Trunk/Spare Tire

Comments

Spare Tire

OK

Jack Tools

OK

Carpeting

Not Reported

Additional Comments

Pictures

