



minor oil leak may be pan seal or rear main



trans case stamp



small dent in oil pan



trans case stamp



engine block stamp



worn seals



pass side seals



rear seat center worn



driver seat cut



trim tag



l/r trunk line



r/r trunk line



r/side door



r/side fender



r/hood line



1/f fender



1/f hood line



left door top edge



1/side door



left door bottom edge